

CNet 3G/4G USB Modem Support List

Updated: 2011/06/14

No.	support date	VID	PID	Brand	Model	Type of 3G service
01	2011/1/7	0x1e0e	0x9200	A-Link	3GU	WCDMA
02	2011/1/7	0x0fa1	0x6010	Aiji System	AU-180	CDMA2000
03	2011/1/7	0x16d5	0x6502	AnyData	ADU-520C	CDMA2000
04	2011/1/7			AnyData	ADU-520A	CDMA2000
05	2011/1/7	0x1bbb	0x0000	Alcatel	X080S	WCDMA
06	2011/1/7	0x1614	0x0800	Amoi	H01	WCDMA
07	2011/1/7	0x1614	0x7002	Amoi	H01A	WCDMA
08	2011/1/7	0x0b05	0x0302	ASUS	T500	WCDMA
09	2011/1/7	0x0805	0x480f	ASUS	T600	WCDMA
10	2011/1/7	0x1a8d	0x1002	BandLuxe	C100	WCDMA
11	2011/1/7			BandLuxe	C100S	WCDMA
12	2011/1/7	0x1a8d	0x1002	BandLuxe	C120	WCDMA
13	2011/1/7	0x1a8d	0x100f	BandLuxe	C170	WCDMA
13	2011/1/7	0x1a8d	0x1009	BandLuxe	C170	WCDMA
14	2011/1/7			BandLuxe	C177	WCDMA
15	2011/1/7	0x1a8d	0x1007	BandLuxe	C180	WCDMA
16	2011/1/7	0x1a8d	0x1009	BandLuxe	C270	WCDMA
17	2011/1/7	0x1a8d	0x100d	BandLuxe	C321	WCDMA
18	2011/1/7	0x1a8d	0x2006	BandLuxe	C331	WCDMA
19	2011/1/7	0x19d2	0x0039	Beng	U31	WCDMA
20	2011/1/7	0x19d2	0x0031	Bmobile (Japan only)	MF626	WCDMA
21	2011/1/7	0x16d8	0x6803	C-motech	CCU-680	CDMA2000
22	2011/1/7	0x2020	0x1005	CSL	U2-TF	WCDMA
23	2011/1/7	0x1ab7	0x2000	Datang	901	TD-SCDMA
24	2011/1/7	0x07d1	0x3e02	D-Link	DWM-156	WCDMA
25	2011/1/24	0x07d1	0x7e0c	D-Link	DWN-156 A2	WCDMA
26	2011/1/7	0x07d1	0x7e11	D-Link	DWM-156 A3	WCDMA
27	2011/1/7	0x07d1	0x3e01	D-Link	DWM-152	WCDMA
28	2011/1/7	0x1e0e	0xce16	D-Link	DWM-162	CDMA2000
29	2011/1/7	0x2077	0x7010	D-Link	DWM-163	CDMA2000
30	2011/1/7	0x1c9e	0x9603	Emobile (Japan only)	C01LC	WCDMA
31	2011/1/7	0x1c9e	0x9900	Emobile (Japan only)	C02LC	WCDMA
32	2011/1/7	0x12d1	0x1003	Emobile (Japan only)	D01HW	WCDMA
33	2011/1/7	0x12d1	0x1003	Emobile (Japan only)	D02HW	WCDMA
34	2011/1/7	0x1c9e	0x6061	Emobile (Japan only)	D11LC	WCDMA
35	2011/1/7			Emobile (Japan only)	D12HW	WCDMA
36	2011/1/7	0x1c9e	0x9104	Emobile (Japan only)	D12LC	WCDMA
37	2011/1/7			Emobile (Japan only)	D21HW	WCDMA
38	2011/1/7	0x1c9e	0x9404	Emobile (Japan only)	D21LC	WCDMA
39	2011/1/7	0x12d1	0x1429	Emobile (Japan only)	D31HW	WCDMA
40	2011/1/7	0x16d5	0x6202	FOMA	A2502	WCDMA
41	2011/1/7	0x1bc7	0x1002	GeoPacket	UM20	WCDMA
42	2011/1/7			HAME	A620	WCDMA
43	2011/1/7	0x12d1	0x1446	HUAWEI	E1550	WCDMA
44	2011/1/7	0x12d1	0x1003	HUAWEI	E1552	WCDMA
45	2011/1/7			HUAWEI	E1553	WCDMA

46	2011/1/7			HUAWEI	E156G	WCDMA
47	2011/1/7			HUAWEI	E160	WCDMA
48	2011/1/7	0x12d1	0x1003	HUAWEI	E160E	WCDMA
49	2011/1/7			HUAWEI	E160X	WCDMA
50	2011/1/7			HUAWEI	E160G	WCDMA
51	2011/1/7			HUAWEI	E161	WCDMA
52	2011/1/7	0x12d1	0x1001	HUAWEI	E166	WCDMA
53	2011/1/7			HUAWEI	E168C	WCDMA
54	2011/1/7			HUAWEI	E169	WCDMA
55	2011/1/7	0x12d1	0x1001	HUAWEI	E169U	WCDMA
56	2011/1/7			HUAWEI	E169G	WCDMA
57	2011/1/7	0x12d1	0x1003	HUAWEI	E170	WCDMA
58	2011/1/7	0x12d1	0x1003	HUAWEI	E172	WCDMA
59	2011/1/7			HUAWEI	E173	WCDMA
60	2011/1/7	0x12d1	0x1003	HUAWEI	E1750	WCDMA
61	2011/1/7			HUAWEI	E176	WCDMA
62	2011/1/7			HUAWEI	E176G	WCDMA
63	2011/1/7	0x12d1	0x1003	HUAWEI	E180	WCDMA
64	2011/1/7	0x12d1	0x14ac	HUAWEI	E1820	WCDMA
65	2011/1/7	0x12d1	0x1003	HUAWEI	E219	WCDMA
66	2011/1/7	0x12d1	0x1003	HUAWEI	E220	WCDMA
67	2011/1/7	0x13d1	0x1004	HUAWEI	E220BIS	WCDMA
68	2011/1/7			HUAWEI	E226	WCDMA
69	2011/1/7	0x12d1	0x1003	HUAWEI	E230	WCDMA
70	2011/1/24	0x12d1	0x140c	HUAWEI	E261	WCDMA
71	2011/1/7			HUAWEI	E270	WCDMA
72	2011/1/7	0x12d1	0x1411	HUAWEI	E510	WCDMA
73	2011/1/7	0x12d1	0x1001	HUAWEI	E600	WCDMA
74	2011/1/7			HUAWEI	E612	WCDMA
75	2011/1/7			HUAWEI	E800	WCDMA
76	2011/1/7	0x12d1	0x1001	HUAWEI	E122	WCDMA
77	2011/1/7	0x12d1	0x1001	HUAWEI	EC122	CDMA2000
78	2011/1/7			HUAWEI	EC1261	CDMA2001
79	2011/1/7	0x12d1	0x140b	HUAWEI	EC1262	CDMA2002
80	2011/1/7	0x12d1	0x1001	HUAWEI	EC1260	CDMA2003
81	2011/1/7	0x12d1	0x140b	HUAWEI	EC1260-india	CDMA2004
82	2011/1/7			HUAWEI	EC150	CDMA2005
83	2011/1/7	0x12d1	0x140c	HUAWEI	EC167	CDMA2006
84	2011/1/7			HUAWEI	EC169	CDMA2007
85	2011/1/7			HUAWEI	EC226	CDMA2008
86	2011/1/7			HUAWEI	EC189	CDMA2009
87	2011/1/7	0x12d1	0x1d09	HUAWEI	ET128	TD-SCDMA
88	2011/1/7			HUAWEI	ET128-2	TD-SCDMA
89	2011/1/7			HUAWEI	ET188	TD-SCDMA
90	2011/1/7			HUAWEI	ET127	TD-SCDMA
91	2011/1/7	0x05c6	0x6061	KPT	WM61	WCDMA
92	2011/1/7	0x1c9e	0x6061	KPT	WM66	WCDMA
93	2011/1/7	0x1004	0x6124	LOMA	L05A	WCDMA
94	2011/1/7	0x1410	0x4400	Novatel	MC930D	WCDMA
95	2011/1/7	0x1410	0x4400	Novatel	MC950D	WCDMA
96	2011/1/7	0x1410	0x2110	Novatel	U720	CDMA2000

97	2011/1/20	0x1410	0x4100	Novatel	U727	WCDMA
98	2011/1/7	0x1410	0x6000	Novatel	USB760	WCDMA/WCDMA
99	2011/1/7	0x0421	0x0612	Nokia	CS-15	WCDMA
100	2011/1/7			Option	GE0202	WCDMA
101	2011/1/7			Option	GT3G Quad	WCDMA
102	2011/1/7	0x0af0	0xd033	Option	Icon 322	WCDMA
103	2011/1/7			Option	Icon 255	WCDMA
104	2011/1/7	0x0af0	0xd157	Option	GI1515	WCDMA
105	2011/1/7	0x05c6	0x6000	Popular	C7-P102HU	WCDMA
106	2011/1/7	0x1d09	0x1011	Pretec	H550	WCDMA
107	2011/1/7			Prolink	PHS100	WCDMA
108	2011/1/7	0x1e0e	0x9100	Prolink	PHS300	WCDMA
109	2011/1/7	0x19d2	0x0151	Prolink	PHS101	WCDMA
110	2011/1/7	0x1da5	0x4512	Qisda	H21	WCDMA
111	2011/1/7	0x1c9e	0x9607	NEXON	X270	WCDMA
112	2011/1/7	0x1c9e	0x9906	NEXON	X450	WCDMA
113	2011/1/7	0x0408	0xea02	NU (OEM by Quanta)	Q101	WCDMA
114	2011/1/7	0x0408	0xea03	NU (OEM by Quanta)	Q110	WCDMA
115	2011/1/7			NU (OEM by Quanta)	Q111	WCDMA
116	2011/1/7	0x0408	0xea09	NU (OEM by Quanta)	Q120	WCDMA
117	2011/1/7	0x1199	0x0025	Sierra	598	CDMA2000
118	2011/1/7	0x1199	0x6851	Sierra	AirCard 881	WCDMA
119	2011/1/7	0x1199	0x6853	Sierra	AirCard 881 E	WCDMA
120	2011/1/7	0x12d1	0x0fff	Sierra	881U	WCDMA
121	2011/1/7	0x1199	0x6850	Sierra	Apex 880	WCDMA
122	2011/1/7	0x1199	0x6852	Sierra	AirCard 880E	WCDMA
123	2011/1/7	0x1199	0x6855	Sierra	Apex 880U	WCDMA
124	2011/1/7	0x1199	0x6880	Sierra	Compass 885	WCDMA
125	2011/1/7	0x1199	0x6890	Sierra	Compass 888	WCDMA
126	2011/1/20	0x1199	0x0023	Sierra	Compass 597	CDMA2000
127	2011/1/20	0x1199	0x0025	Sierra	USB 598	CDMA2000
128	2011/1/7	0x1c9e	0x9603	Softbank (Japan)	C01LC	WCDMA
129	2011/1/7			Solomon	S3GM-645	WCDMA
130	2011/1/7			Solomon	S3GM-690	WCDMA
131	2011/1/7	0x0fce	0xd0cf	Sony Ericsson	MD300	WCDMA
132	2011/1/7	0x0fce	0xd0e1	Sony Ericsson	MD400	WCDMA
133	2011/1/7			StarHub (Singapore)	MF626	WCDMA
134	2011/1/7			Suncomm	nonebrand	WCDMA
135	2011/1/20	0x1d09	0x1010	S-TEK	S-TEK 774839	CDMA2000
136	2011/1/7	0x1e89	0xf001	S-TEK	S-TEK 774838	WCDMA
137	2011/1/7	0x05c6	0x9000	SWM	U9	WCDMA
138	2011/1/7	0x05c6	0x9002	SWM	U11	WCDMA
139	2011/1/7	0x1d12	0x5105	TELTONIKA	UM5100	WCDMA
140	2011/2/21	0x106c	0x3711	Verizon Wireless	UM150	CDMA2000
141	2011/1/20	0x1199	0x0120	Verizon Wireless	AC595U	CDMA2000
142	2011/1/7			Vodafone	E272	WCDMA
143	2011/1/7	0x19d2	0x0055	Vodafone	K3520-Z	WCDMA
144	2011/1/7	0x19d2	0x0063	Vodafone	K3565-Z	WCDMA
145	2011/1/7			Vodafone	K3715	WCDMA
146	2011/1/7	0x0af0	0x7501	Vodafone	K3760	WCDMA
147	2011/1/7	0x12d1	0x1465	Vodafone	K3765	WCDMA

148	2011/1/7	0x12d1	0x1464	Vodafone	K4505	WCDMA
149	2011/1/7	0x19d2	0x2003	ZTE	MF100	WCDMA
150	2011/1/7	0x19d2	0x2000	ZTE	MF110	WCDMA
151	2011/1/7			ZTE	MF112	WCDMA
152	2011/1/7	0x19d2	0x0117	ZTE	MF180	WCDMA
153	2011/1/7			ZTE	MF620	WCDMA
154	2011/1/7			ZTE	MF622	WCDMA
155	2011/1/7	0x19d2	0x0031	ZTE	MF626	WCDMA
156	2011/1/7	0x19d2	0x0033	ZTE	MF626(Russia)	WCDMA
157	2011/1/7			ZTE	MF627	WCDMA
158	2011/1/7	0x19d2	0x2003	ZTE	MF627(Phillipine)	WCDMA
159	2011/1/7	0x19d2	0x0015	ZTE	MF628	WCDMA
160	2011/1/7	0x19d2	0x0031	ZTE	MF633	WCDMA
161	2011/1/7	0x19d2	0x0016	ZTE	MF636-BKIC (Japan)	WCDMA
162	2011/1/7	0x19d2	0x0031	ZTE	MF636	WCDMA
163	2011/1/7	0x19d2	0x0033	ZTE	MF636(UK)	WCDMA
164	2011/1/7			ZTE	MF637	WCDMA
165	2011/1/7	0x19d2	0x0031	ZTE	MF637U	WCDMA
166	2011/1/7	0x19d2	0x0016	ZTE	MF662	WCDMA
167	2011/1/7	0x19d2	0x0017	ZTE	MF668	WCDMA
168	2011/1/7	0x19d2	0xffff1	ZTE	AC2726	CDMA2000
169	2011/1/7			ZTE	AC2736	CDMA2000
170	2011/1/7			ZTE	AC2746	CDMA2000
171	2011/1/7	0x19d2	0xffff1	ZTE	AC2766	CDMA2000
172	2011/2/16	0x19d2	0xffffe	ZTE	AC8710	CDMA2000
173	2011/1/7			ZTE	AC560	CDMA2000
174	2011/1/7	0x19d2	0x0073	ZTE	AC580	CDMA2000
175	2011/1/7	0x19d2	0x0073	ZTE	AC581	CDMA2000
176	2011/1/7	0x19d2	0x0094	ZTE	AC590	CDMA2000
177	2011/1/7	0x19d2	0x0034	ZTE	MU330	TD-SCDMA
178	2011/1/7	0x19d2	0x0020	ZTE	MU350	TD-SCDMA
179	2011/1/7	0x19d2	0x0020	ZTE	MU351	TD-SCDMA
180	2011/1/7	0x19d2	0x0079	ZTE	MU356	TD-SCDMA
181	2011/1/7			Far Eastone	MMI31	WCDMA
182	2011/1/7	0x201e	0x2009	Haier	CE100	CDMA2000
183	2011/1/20	0x0d08	0x0300	Cricket	UM100C	CDMA2000
184	2011/1/20	0x106c	0x3717	Cricket	UM185C	CDMA2000
185	2011/1/20	0x1199	0x68a3	AT&T	USBConnect Lightning	WCDMA
186	2011/2/16	0x0f3d	0x68a3	AT&T	USBConnect Shockwave	WCDMA
187	2011/1/7	0x1c9e	0x9202	MYWAVE	SW006	WCDMA
188	2011/1/7	0x19d2	0x0002	TIM ONDA	MT505UP	WCDMA
189	2011/1/20	0x21f5	0x2008	Zhongwei	U200	CDMA2000
190	2011/2/16	0x201e	0x1010	etisalat	etisalat	WCDMA
191	2011/3/2	0x1410	0x6002	Novatel	MC760	CDMA2000
192	2011/3/2	0x1199	0x0301	Sierra	USB250U	CDMA2000
193	2011/3/2	0x1c9e	0x9605	MODEM SPEEDUP	su9500u	WCDMA
194	2011/3/2	0x19d2	0x0017	ZTE	MF190	WCDMA
195	2011/3/2	0x201e	0x2009	Haier	C260	CDMA2000
196	2011/3/15	0x106c	0x3714	Verizon Wireless	UM175	CDMA2000
197	2011/3/21	0x0408	0xea04	speedup	su8500u	CDMA2000
198	2011/3/22	0x1e0e	0xce28	speedup	SU 7000	CDMA2000

199	2011/3/22	0x1c9e	0x9605	speedup	SU 8650U	WCDMA
200	2011/3/22	0x1c9e	0x9800	speedup	SU 8900U	WCDMA
201	2011/3/22	0x2020	0x1008	speedup	SU 9300U	WCDMA
202	2011/3/22	0x1c9e	0x9613	speedup	SU 9800	WCDMA
203	2011/3/22	0x1c9e	0x9000	speedup	SU 9000XE	WCDMA
204	2011/3/22	0x201e	0x2009	Speedup	Olive	CDMA2000
205	2011/3/22	0x0421	0x0623	Nokia	CS17	WCDMA
206	2011/3/23	0x0421	0x062d	Nokia	CS19	WCDMA
207	2011/4/11	0x1e0e	0xce16	D-LINK	DWM-162-U5	CDMA2000
208	2011/4/12	0x0af0	0xd055	OPTION	ICON 505	WCDMA
209	2011/4/12	0x0b05	0x1712	Nokia	CS-12	WCDMA(HSDPA)
210	2011/4/18	0x1d09	0x1026	Bmobile	Brunei Bmobile	WCDMA
211	2011/4/27	0x1199	0x68a3	Sierra	AirCard309	WCDMA
212	2011/4/27	0x19d2	0x2000	Wellcomm	W118G	WCDMA
213	2011/5/26	0x12d1	0x1001	HUAWEI	E181	WCDMA
214	2011/5/26	0x0eba	0x210a	Time Power	WM2080a-110	CDMA2000
215	2011/5/26	0x19d2	0x0117	ZTE	MF631	WCDMA
216	2011/5/26	0x230d	0x0007	Linktop	U302	WCDMA
	2011/5/30	0x230d	0x0001	Linktop	U302(new fw)	WCDMA
217	2011/5/30	0x12d1	0x140c	Huawei	E1731	WCDMA
218	2011/5/30	0x1c9e	0x9605	Longcheer	WM66a	WCDMA

LTE Dongle

No.	support date	VID	PID	Brand	Model	Type of 3G service
1	2011/5/26	0x1004	0x618f	DOCOMO	L-02C	
2	2011/5/26	0x19d2	0x1525	ZTE	MF591	